

**ANNEXURE I**  
**REPORT OF TOXIC**  
**ELEMENT ANALYSIS**

MOEF letter No:- J-11011/231/2009-IA II(I) Dated 8<sup>th</sup> June 2009

Plot No. 97, Sector 1/A  
 Gandhidham - 370201  
 [ CIN : U51909WB1956PTC023037 ]  
 T : 02836 226225  
 F : 02836 226225  
 E : gandhidham@mitrask.co.in

Certificate No. GDM/15-16/C-0281  
 Ref. No. : SJ/GAN/SL-2015/00001

Date: 21.07.2015

### CERTIFICATE OF ANALYSIS


We hereby certify that One sample describe as "SLAG" submitted to us by M/s. GALLANT METALS LTD - GANDHIDHAM, on 04.07.2015 has been analyzed with the following results.

#### Analysis Result:-

PARAMETERS	SLAG
Vanadium (V)	0.024 %
Chromium (Cr)	0.25 %
Barium (Ba)	0.74 %
Nickel (Ni)	0.0007 %
Copper (Cu)	0.0041 %
Zinc (Zn)	0.0047 %
Arsenic (As)	Less than 28 µg/kg
Lead (Pb)	0.0003 %
Molybdenum (Mo)	0.0018 %
Mercury (Hg)	Less than 9 µg/kg
Cobalt (Co)	0.0005 %



M/s. GALLANT METALS LTD.,  
 GANDHIDHAM

Checked By :



M/s. Mitra S. K. Private Limited

Authorized Signatory



Plot No: 97, Sector 1/A  
Gandhinagar - 370201  
[CIN: U51909WB1956PTC023037]

T: 02836 226225  
F: 02836 226225  
E: gandhinagar@mitrask.com

Certificate No. : GDM/17-18/C-427  
Ref No: SJ/GAN/FA-2017/00001

Date: 21.07.2017


**CERTIFICATE OF ANALYSIS**

We hereby certify that TWO (02) sample described as "FLY ASH" submitted to us by M/s. GALLENT METAL LIMITED on 10.07.2017 has been analyzed with the following results:-

Analysis Result of FLY ASH:

PARAMETERS	SAMPLE MARK	
	SAMPLE - 01	SAMPLE - 02
VANADIUM	0.0057	0.0039
CHROMIUM	0.0052	0.004
BARIUM	0.07	0.09
NICKEL	0.0002	0.0004
COPPER	0.0022	0.0025
ZINC	0.0035	0.0025
LEAD	0.0099	< 0.0001
ARSENIC	< 0.0001	< 0.0001
MOLYBDENUM	< 0.0001	< 0.0001
MERCURY	< 0.0001	< 0.0001
COBALT	< 0.0001	0.0014

TO,  
M/S GALLENT METAL LIMITED.

Checked by: 

M/s. Mitra S. K. Private Limited

Authorized Signatory

